

## Welding a Steel Rose - Greg Kraft

### Safety First:

Wear a long sleeved cotton shirt, long legged blue jeans (or other sturdy long legged work pants), closed toed leather shoes or boots.

Bring: leather work gloves, welding helmet if you have one, a lunch or snack and refillable water bottle.

Instructor will provide: TIG welder and welding material, welding helmets, safety glasses, extra gloves, cutting and bending hand tools, vise, anvil, electric drill and angle grinder.